









TOOLS INCLUDED



Attach Support Angle onto the Support Bar and Leg. Insert **B** Bolts, as shown. Screw Bolt **C** into Support Angle and Bar. Tighten **B** Bolts with **A** Nuts.



Attach Support Angle onto the Support Bar and Leg. Insert **B** Bolts, as shown. Screw Bolt **C** into Support Angle and Bar. Tighten **B** Bolts with **A** Nuts.



IMPORTED BY:
FUNNIVATION (HK) LTD.
UNIT 03-04, 21/F,
EIGHT COMMERCIAL TOWER,
8 SUN YIP STREET,
CHAI WAN, HONG KONG